Base Status Code	Possible Additional Numbers / Explanation / Action
31	 Release the Alt 1 or Alt 2 pushbutton, or Request help from your technical support group or help desk.
36	IML hardware failure: file adapter.
	 Re-IML. Request service for the control unit.
40	This is a normal Alt 1 IML prompt for additional input.
	The Alt 1 IML procedures provide the required responses (refer to "Alt 1 IML Tests" on page 3-110).
42 - 94	IML hardware failure: processor or storage card.
	 Re-IML. Request service for the control unit.
96 - 98	Invalid response to the Alt 1 IML 40 prompt.
	 Re-IML. Try the keypad entry again. Request help from your technical support group or help desk.
101 - 114	IML hardware failure: processor or file adapter.
	 Re-IML. Request help from your technical support group or help desk.
117	IML hardware failure: diskette drive or media.
	 Make sure that the correct diskette is correctly installed (refer to "Diskettes and Diskette Drives" on page 2-13 for the correct way to insert diskettes). Insert a backup diskette, and try the Alt 1 IML again. If the problem returns, run Alt 2 IML tests (refer to "Alt 2 IML Tests" on page 3-108). Request help from your technical support group or help desk.
120	During an Alt 2 IML, a Control or Utility diskette was not found in diskette drive 01.
	 Insert a Control or Utility diskette into diskette drive 01. Try an Alt 2 IML again. Try using a backup copy of the diskette. Request help from your technical support group or help desk.
121	A not-ready drive condition was detected during an Alt 1 or Alt 2 IML.
	 Make sure that the diskette is correctly installed. For an Alt 2 IML, the diskette must be in drive 01. Make sure that the diskette drive lever is closed. Try the Alt 1 or Alt 2 IML again. Request help from your technical support group or help desk.
123	IML hardware failure: diskette drive or file adapter.
	 Re-IML. Request help from your technical support group or help desk.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action	
124	IML hardware failure: diskette drive or media.	
	 Re-IML with the backup Control diskette. Request help from your technical support group or help desk. 	
125	IML hardware failure: diskette drive.	
	Re-IML.Request help from your technical support group or help desk.	
130	During a normal IML, the Control diskette was not found.	
	 Make sure that a customized Control diskette is correctly inserted into the diskette drive, and try to IML again (refer to "Diskettes and Diskette Drives" on page 2-13 for the correct way to insert diskettes). Try another Control diskette. Re-IML. Request help from your technical support group or help desk. 	
131	An Alt 1 IML was performed with a diskette that does not have IML capabilities.	
	 Insert a valid Control or Utility diskette, and re-IML. Request help from your technical support group or help desk. 	
2%%	There is a mismatch between customization and the hardware that is installed on the 3174 control unit.	
	Request help from your technical support group or help desk.	
200 - 299	3270 terminal failure (display, printer, selector pen, etc.).	
	 Press RESET at the affected terminal and try the operation again. At the affected terminal, set the Normal/Test switch from Normal to Test and back again. Then try the operation again. At the affected terminal, switch the power off, then on, and try the operation again. Request help from your technical support group or help desk. 	
301 - 311	3174 hardware failure.	
	 Press RESET at the affected terminal. Try the operation again. Re-IML. 	
	Warning: An IML disrupts all operating terminals.	
	 Run an Alt 2 IML Test (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 	
313	3174 hardware failure: operator panel.	
·	 Press RESET at the affected terminal. No further recovery is possible at this time. Repair action is mandatory before the next IML. Request service for the control unit. 	

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
315 - 331	3174 hardware failure.
	 Press RESET at the affected terminal. Try the operation again. Re-IML.
	Warning: An IML disrupts all operating terminals.
	 Run an Alt 2 IML Test (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
335	3174 hardware failure, Encrypt/Decrypt feature.
	Note: The control unit can still be operational without the Encrypt/Decrypt Adapter.
	 Press RESET at the affected terminal. Try the operation again. Re-IML.
	Warning: An IML disrupts all operating terminals.
	 Run an Alt 2 IML Test (refer to "Alt 2 IML Tests" on page 3-108). Request help from your technical support group or help desk.
336	3174 hardware failure, Encrypt/Decrypt battery.
	Replace the battery on the Encrypt/Decrypt adapter card.
340	A Token-Ring Adapter error condition has been cleared.
	No action is required.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
341	01HG - 02HG A Token-Ring Adapter hardware failure occurred.
	 Contact the host operator to return the link(s) to service. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
	Warning: An IML disrupts all operating terminals.
	• Request help from your technical support group or help desk.
	03HG - 06HG A Token-Ring Adapter hardware failure occurred.
	• Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
	Warning: An IML disrupts all operating terminals.
	• Request help from your technical support group or help desk.
	07HG - 20HG A Token-Ring Adapter hardware failure occurred.
	 Contact the host operator to return the link(s) to service. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
	Warning: An IML disrupts all operating terminals.
	• Request help from your technical support group or help desk.
	21HG - 22HG A Token-Ring Adapter hardware failure occurred.
	• Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
	Warning: An IML disrupts all operating terminals.
	 Request help from your technical support group or help desk.
	53HG - 56HG A temporary Token-Ring Adapter failure occurred.
	 No repair actions are required if the control unit is operating normally. If it is not working normally, go to the next step. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
	Warning: An IML disrupts all operating terminals.
	Request help from your technical support group or help desk.
351 and	An ASCII Adapter hardware or microcode failure occurred.
352	 Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform an ASCII Port Wrap Test on the failing adapter port (HG and port) indicated in the terminal message. Re-IML.
	Warning: An IML disrupts all operating terminals.
	 Run an Alt 2 IML Test (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
380	01HG - 20HG A Token-Ring Adapter microcode failure occurred.
	 Contact the host operator to return the link(s) to service. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
	60HG - 96HG A temporary Token-Ring Adapter microcode failure occurred.
	 No action is required if the control unit is operating normally. If it is not working normally, go to the next step. Contact the host operator to reactivate the links. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request help from your technical support group or help desk.
381	0xHG - 21HG A 3174 microcode failure occurred.
	 Re-IML. Run an Alt 2 IML Test (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
	5xHG A 3174 microcode failure occurred.
	No action is required unless your operation is impaired.
	 Re-IML. Run an Alt 2 IML Test (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
382	3174 operational hardware failure.
	 Press RESET at the affected terminal. Try the operation again. Re-IML.
	Warning: An IML disrupts all operating terminals.
	 Run an Alt 2 IML Test (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
384	A Downstream Load (DSL) diskette is not present in the 3174.
	 Remove the DSL diskette (usually in drive 2) and reinsert it. Certain terminals may require power-on. Try another DSL diskette. If the problem continues, re-IML.
	Warning: An IML disrupts all operating terminals.
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
385	00HG A 3174 diskette drive is not ready.
	 Remove the diskette and check that it is the correct diskette. Insert the correct diskette into the drive to start again. If the problem occurred during IML, then re-IML.
	Warning: An IML disrupts all operating terminals.
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
	01HG A 3174 diskette drive is not ready.
	 Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette. Insert the correct diskette into the drive to start again. If the problem continues, re-IML.
	Warning: An IML disrupts all operating terminals.
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
	02HG A 3174 diskette drive is not ready during an online test.
	 Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette. Insert the correct diskette into the drive to start again. Select the online test again. If the problem continues, re-IML.
	Warning: An IML disrupts all operating terminals.
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
	03HG and 04HG A 3174 diskette drive is not ready during customizing or IML.
	 Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette. Insert the correct diskette into the drive and re-IML to start again. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
	05HG The 3174 diskette drive containing the Downstream Load (DSL) diskette is not ready.
	 Remove the DSL diskette (usually in drive 2) and check that it really is the DSL diskette. Insert the correct diskette into the drive and close the drive lever.

- Insert the correct diskette into the drive and close the drive lever.
- If the problem continues, replace the DSL diskette with a duplicate.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action		
385 (cont.)	06HG The 3174 diskette drive containing the Distributed Function Terminal (DFT) Dump diskette is not ready.		
	 Remove the Dump diskette (usually in drive 1) and check that it really is the Dump diskette. Insert the correct diskette into the drive and select the dump again. If the problem continues, re-IML. 		
	Warning: An IML disrupts all operating terminals.		
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
	07HG The 3174 diskette drive is not ready during offline diagnostics.		
	 Remove the Utility diskette (usually in drive 1) and check that it really is the Utility diskette. Insert the correct diskette into the drive, press ENTER, and select the test again. If the problem continues, re-IML. 		
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
	08HG The 3174 diskette drive is not ready during an offline dump, and the dump has been lost.		
	 Initiate the dump again at the next microcode failure. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
	09HG The 3174 diskette drive is not ready during an offline dump.		
	 Remove the Control or Dump diskette (usually in drive 1) and check that you are using the correct one. 		
	 Insert the correct diskette into the drive to start the dump again. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
387	The wrong diskette is being used in the control unit for Downstream Load (DSL).		
	 Remove the DSL diskette (usually in drive 2) and check that it really is the DSL diskette. Insert the DSL diskette into the drive and power-on the Distributed Function Terminal to start again. 		
	 If the problem continues, re-IML. Warning: An IML disrupts all operating terminals. 		
	, , ,		
	• Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).		

• Request service for the control unit.

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action		
388	00HG A 3174 diskette media failure.		
	 Remove the diskette. Insert another diskette into the drive. If the problem occurred during IML, then re-IML. 		
	Warning: An IML disrupts all operating terminals.		
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
	01HG A 3174 diskette media failure occurred during the logging of records.		
	 Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette. Insert the correct diskette into the drive to start again. If the problem continues, repeat the procedures above with a duplicate Control diskette. If the problem continues, re-IML. 		
	Warning: An IML disrupts all operating terminals.		
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
	02HG A 3174 diskette media failure occurred during an online test.		
	 Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette. Insert the correct diskette into the drive and select the test again. If the problem continues, repeat the procedures above with a duplicate Control diskette. If the problem continues, re-IML. 		
	Warning: An IML disrupts all operating terminals.		
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
	03HG and 04HG A 3174 diskette media failure occurred during an IML or customizing.		
	 Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette. Insert the correct diskette into the drive and re-IML to start again. If the problem continues, repeat the procedures above with a duplicate Control diskette. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
	05HG A 3174 diskette media failure occurred during a Downstream Load (DSL) operation.		
	 Remove the DSL diskette (usually in drive 2) and check that it really is a DSL diskette. Insert the correct diskette into the drive and power-on the Distributed Function Terminal to start again. If the problem continues, repeat the procedures above with a duplicate DSL diskette. 		

Warning: An IML disrupts all operating terminals.

- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.
- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action		
388 (cont.)	06HG A 3174 diskette media failure occurred during a Distributed Function Terminal dump.		
	 Remove the Dump diskette (usually in drive 1) and check that it really is the Dump diskette. Insert the correct diskette into the drive and select the dump again. If the problem continues, repeat the procedures above with a different Dump diskette. If the problem continues, re-IML. 		
	Warning: An IML disrupts all operating terminals.		
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
	07HG A 3174 diskette media failure occurred during offline diagnostics.		
	 Remove the Utility diskette (usually in drive 1) and check that it really is the Utility diskette. Insert the correct diskette into the drive, press ENTER, and select the test again. If the problem continues, repeat the procedures above with a different Utility diskette. If the problem continues, re-IML. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
	08HG A 3174 diskette media failure occurred during an offline dump, and the dump has been lost.		
	 Initiate the dump again at the next microcode failure. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
	09HG A 3174 diskette media failure occurred during an offline dump.		
	 Remove the Control or Dump diskette (usually in drive 1) and check that you are using the correct one. Insert the correct diskette into the drive to start the dump again. If the problem continues, repeat the procedures above with a different Dump diskette or a duplicate Control diskette. 		
	Note: If you use another Dump diskette, part of the dump will be on the original diskette and the rest will be on the second diskette.		
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 		
389	01HG - 04HG A 3174 file adapter failure occurred.		
	• No further recovery is possible at this time. Repair action is mandatory before the next IML.		
	Warning: Do not turn off Distributed Function Terminals for which downstream loads are required.		
	• Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108) to isolate the cause of the failure.		
	Warning: An IML disrupts all operating terminals.		

Warning: An IML disrupts all operating terminals.

• Request service for the control unit.

51HG - 54HG A 3174 diskette error.

• No action to be performed.

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
390	00HG A 3174 diskette failure: file not found.
	 Remove the diskette and check that it is the correct diskette. Insert the correct diskette into the drive to start again. If the problem occurred during IML, then re-IML.
	Warning: An IML disrupts all operating terminals.
	 If the problem continues, repeat the procedures above with a duplicate diskette. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
	01HG A 3174 diskette failure occurred during the logging of records: file not found.
	 Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette. Insert the correct diskette into the drive to start again. If the problem continues, repeat the procedures above with a duplicate Control diskette. If the problem continues, re-IML.
	Warning: An IML disrupts all operating terminals.
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
	02HG A 3174 diskette failure occurred after an online test was requested: file not found.
	 Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette. Insert the correct diskette into the drive and select the test again. If the problem continues, repeat the procedures above with a duplicate Control diskette. If the problem continues, re-IML.
	Warning: An IML disrupts all operating terminals.
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
	03HG and 04HG A 3174 diskette failure occurred during an IML or customizing: file not found.
	 Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette. Insert the correct diskette into the drive and re-IML to start again. If the problem continues, repeat the procedures above with a duplicate Control diskette. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).

• Request service for the control unit.

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base	Possible
Status	Additional
Code	Numbers / Explanation / Action

390 (cont.) 05HG A 3174 diskette failure occurred during a Downstream Load (DSL): file not found.

- Remove the DSL diskette (usually in drive 2) and check that it really is a DSL diskette.
- Insert the correct diskette into the drive and power-on the Distributed Function Terminal to start
- If the problem continues, repeat the procedures above with a duplicate DSL diskette.
- If the problem continues, re-IML.

Warning: An IML disrupts all operating terminals.

- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

06HG A 3174 diskette failure occurred during a DFT dump: file not found.

- Remove the Dump diskette (usually in drive 1) and check that it really is the Dump diskette.
- Insert the correct diskette into the drive and select the dump again.
- If the problem continues, repeat the procedures above with a different Dump diskette.
- If the problem continues, re-IML.

Warning: An IML disrupts all operating terminals.

- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

07HG A 3174 diskette failure occurred during offline diagnostics: file not found.

- Remove the Utility diskette (usually in drive 1) and check that it is the correct diskette.
- Insert the correct diskette into the drive, press ENTER, and select the test again.
- If the problem continues, repeat the procedures above with a different Utility diskette.
- If the problem continues, re-IML.
- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

08HG A 3174 failure occurred during an offline dump, and the dump has been lost.

- Initiate the dump again at the next microcode failure.
- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

09HG A 3174 diskette failure occurred during an offline dump: file not found.

- Remove the Control or Dump diskette and check that you are using the correct one.
- Insert the correct diskette into the drive to start the dump again.
- If the problem continues, repeat the procedures above with a different Dump diskette or a duplicate Control diskette. Note that, if you use another Dump diskette, part of the dump will be on the original diskette and the rest will be on the second diskette.
- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.
- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
- When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more
- than 10 seconds, the code indicates an error. For an error, perform the appropriate actions

Status Codes

Base	Possible	
Status	Additional	
Code	Numbers / Explanation / Action	

391 00HG A 3174 diskette failure: a write-protect error was detected.

- · Obtain a diskette that is not write-protected, or remove write-protection from the current diskette.
- · Insert the diskette into the drive to start again.
- If the problem occurred during IML, then re-IML.

Warning: An IML disrupts all operating terminals.

- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- · Request service for the control unit.

01HG A 3174 diskette failure: a write-protect error was detected during the logging of records.

- Remove the Control diskette (usually in drive 1).
- · Obtain a diskette that is not write-protected, or remove write-protection from the current diskette.
- Insert the diskette into the drive to start again.
- If the problem continues, repeat the procedures above with a duplicate Control diskette.
- · If the problem continues, re-IML.

Warning: An IML disrupts all operating terminals.

- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- · Request service for the control unit.

02HG A 3174 diskette failure: a write-protect error was detected during an online test.

- Remove the Control diskette (usually in drive 1).
- · Obtain a diskette that is not write-protected, or remove write-protection from the current diskette.
- · Insert the diskette into the drive and select the test again.
- If the problem continues, repeat the procedures above with a duplicate Control diskette.
- If the problem continues, re-IML.

Warning: An IML disrupts all operating terminals.

- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

03HG and 04HG A 3174 diskette failure: a write-protect error was detected during an IML or customizing.

- Remove the Control diskette (usually in drive 1).
- · Obtain a diskette that is not write-protected, or remove write-protection from the current diskette.
- Insert the diskette into the drive and re-IML to start again.
- If the problem continues, repeat the procedures above with a duplicate Control diskette.
- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- · Request service for the control unit.

[•] Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.

When requesting service, be sure to give the status code and additional numbers to the service personnel.

[•] Some status codes are normal progress or completion messages; if the **Status Code** remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base	Possible
Status	Additional
Code	Numbers / Explanation / Action

391 (cont.)

05HG A 3174 diskette failure: a write-protect error was detected during a Downstream Load (DSL) operation.

- Remove the DSL diskette (usually in drive 2).
- Obtain a diskette that is not write-protected, or remove write-protection from the current diskette.
- · Insert the diskette into the drive and power-on the Distributed Function Terminal to start again.
- If the problem continues, repeat the procedures above with a duplicate DSL diskette.
- If the problem continues, re-IML.

Warning: An IML disrupts all operating terminals.

- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- · Request service for the control unit.

06HG A 3174 diskette failure: a write-protect error was detected during an online dump.

- · Remove the Dump diskette (usually in drive 1).
- Obtain a diskette that is not write-protected, or remove write-protection from the current diskette.
- Insert the diskette into the drive and select the dump again.
- If the problem continues, repeat the procedures above with a different Dump diskette.
- · If the problem continues, re-IML.

Warning: An IML disrupts all operating terminals.

- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- · Request service for the control unit.

07HG A 3174 diskette failure: a write-protect error was detected during offline diagnostics.

- Remove the Utility diskette (usually in drive 1).
- · Obtain a diskette that is not write-protected, or remove write-protection from the current diskette.
- · Insert the diskette into the drive, press ENTER, and select the test again.
- If the problem continues, repeat the procedures above with a different Utility diskette.
- If the problem continues, re-IML.
- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- · Request service for the control unit.

08HG A 3174 diskette failure: a write-protect error was detected during an offline dump, and the dump has been lost.

- Initiate the dump again at the next microcode failure. Use a different Dump diskette that is not write-protected, or remove write-protection from the current diskette.
- · Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- · Request service for the control unit.

09HG A 3174 diskette failure: a write-protect error was detected during an offline dump.

- Remove the Control or Dump diskette (usually in drive 1).
- Obtain a diskette that is not write-protected, or remove write-protection from the current diskette.
- Insert the diskette into the drive to start again.
- · Request service for the control unit.
- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
- When requesting service, be sure to give the status code and additional numbers to the service personnel.
- Some status codes are normal progress or completion messages; if the **Status Code** remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action	
392	00HG A 3174 diskette error occurred.	
	 Remove the diskette and check that it is the correct diskette. Insert the diskette into the drive to start again. If the problem occurred during IML, then re-IML. 	
	Warning: An IML disrupts all operating terminals.	
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 	
	01HG A 3174 diskette error occurred during the logging of records.	
	 Remove the Control diskette (usually in drive 1). Insert a duplicate Control diskette into the drive to start again. If the problem continues, re-IML. 	
	Warning: An IML disrupts all operating terminals.	
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 	
	02HG A 3174 diskette error occurred during an online test.	
.	 Remove the Control diskette (usually in drive 1). Insert a duplicate Control diskette into the drive to start again. If the problem continues, re-IML. 	
	Warning: An IML disrupts all operating terminals.	
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit. 	

- Re-IML means to try to make the control unit operational; refer to page 4-18upp. for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base	Possible
Status	Additional
Code	Numbers / Explanation / Action
392 (cont.)	03HG and 04HG 4 3174 diskette error was detected during an IMI or customizing

- Remove the Control diskette (usually in drive 1).
- Insert a duplicate Control diskette into the drive and re-IML to start again.
- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

05HG A 3174 diskette error occurred during a Downstream Load (DSL) operation.

- Remove the DSL diskette (usually in drive 2).
- Insert a duplicate DSL diskette into the drive and power-on the Distributed Function Terminal to start again.
- If the problem continues, re-IML.

Warning: An IML disrupts all operating terminals.

- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

06HG A 3174 diskette error occurred during an online dump.

- Remove the Dump diskette (usually in drive 1).
- Insert a different Dump diskette into the drive and select the dump again.
- If the problem continues, re-IML.

Warning: An IML disrupts all operating terminals.

- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

07HG A 3174 diskette error occurred during diagnostics.

- Remove the Utility diskette (usually in drive 1) and check that it really is the Utility diskette.
- Insert a different Utility diskette into the drive, press ENTER, and select the test again.
- If the problem continues, re-IML.
- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

08HG A 3174 diskette error was detected during an offline dump, and the dump has been lost.

- · Initiate the dump again at the next microcode failure.
- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

[•] Re-IML means to try to make the control unit operational; refer to page 4-19upp. for the correct actions.

[•] When requesting service, be sure to give the status code and additional numbers to the service personnel.

Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
393	00HG A 3174 diskette was changed.
	 Remove the diskette and check that it is the correct diskette. Insert the correct diskette into the drive and close the drive lever. If the problem occurred during IML, then re-IML.
	Warning: An IML disrupts all operating terminals.
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
	01HG A 3174 diskette was changed during the logging of records.
	 Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette. Insert the correct diskette into the drive to start again. If the problem continues, re-IML.
	Warning: An IML disrupts all operating terminals.
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
	02HG A 3174 diskette was changed during an online test.
	 Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette. Insert the correct diskette into the drive and select the test again. If the problem continues, re-IML.
	Warning: An IML disrupts all operating terminals.
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.

<sup>Re-IML means to try to make the control unit operational; refer to page 4-20upp. for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Possible
Status Additional
Code Numbers / Explanation / Action

393 (cont.) 03HG and 04HG A 3174 diskette was changed during an IML or customizing.

- Remove the Control diskette (usually in drive 1) and check that it really is the Control diskette.
- Insert the correct diskette into the drive and re-IML to start again.
- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

05HG A 3174 diskette was changed while a Downstream Load (DSL) was being tried.

The DSL resumes automatically.

06HG A 3174 diskette was changed during a Distributed Function Terminal dump.

The dump resumes automatically.

07HG A 3174 diskette was changed during diagnostics; the diagnostics have ended before completion.

- Press Enter to obtain the 4001 prompt, and select the test again.
- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

08HG A 3174 diskette was changed during an offline dump, and the dump has been lost.

- Initiate the dump again at the next microcode failure.
- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- · Request service for the control unit.

[•] Re-IML means to try to make the control unit operational; refer to page 4-21upp. for the correct actions.

[•] When requesting service, be sure to give the status code and additional numbers to the service personnel.

[•] Some status codes are normal progress or completion messages; if the **Status Code** remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action	
399	01HG The 3174 is configured for ASCII, but the ASCII Adapter is not installed.	
	Note: The 3174 is operational but will not execute ASCII functions.	
	• Request help from your technical support group or help desk.	

03HG A 3174 diskette error occurred, and the ASCII Adapter was not initialized.

Note: The 3174 is operational but will not execute ASCII functions.

- · Remove the diskette and check that it is the 3174 ASYNC Emulation Adapter diskette.
- · Insert this diskette into the drive.
- · Re-IML.

Warning: An IML disrupts all operating terminals.

· Request help from your technical support group or help desk.

04HG A 3174 diskette error occurred. The Control diskette is not compatible with the level of the **3174** ASYNC Emulation Adapter diskette.

Note: The 3174 is operational but will not execute ASCII functions.

- · Obtain a Control diskette that is compatible with the 3174 ASYNC Emulation Adapter diskette.
- · Insert this Control diskette into the drive.
- · Re-IML.

Warning: An IML disrupts all operating terminals.

· Request help from your technical support group or help desk.

05HG The 3174 is still operational; however, the **3270 Terminal Adapter** is missing, defective. or not properly installed.

• If you need to use the 3270 terminals, re-IML.

Warning: An IML disrupts all operating terminals.

- Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
- Request service for the control unit.

06HG A 3174 diskette containing ASYNC Emulation Adapter code was not found.

Note: The 3174 is operational but will not execute ASCII functions.

- · Check that the diskettes are labeled Control Diskette and 3174 ASYNC Emulation Adapter Diskette.
- Insert the correct diskettes into the drives.
- · Re-IML.

Warning: An IML disrupts all operating terminals.

• Request help from your technical support group or help desk.

• Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.

[•] When requesting service, be sure to give the status code and additional numbers to the service personnel.

[•] Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
399 (cont.)	07HG Certain 3174 terminal users may not be able to access all the sessions that were configured.
	Note: Additional storage is required.
	• Request help from your technical support group or help desk.
	08HG A missing or disconnected ASCII Adapter cable.
	 Connect or replace the adapter cable. Request service for the control unit.
	09HG IML hardware configuration failure.
	A Terminal Multiplexer Adapter (TMA) is installed but does not appear to be connected to a Terminal Adapter port.
	1. Press Advance twice — the first two digits in the Status display (after pressing of Advance twice) identify the card location number of the affected TMA. Repeat this procedure, recording the first two digits that appear in the Status display, until the Status display is blank.
	2. Press the latch-release pushbutton on the left-center edge of the front door, and open the door (refer to Figure 2-1 on page 2-2, if necessary).
	3. Make sure that the jumper cables are correctly connected both to the Terminal Adapter (card location 22 [L models] or 23 [R models]) and to the top coaxial connector on the associated TMAs (possible card locations are 15, 16, 11 or 23, and 12, 17, and 24).
	4. To proceed with the IML, and to bring up those terminals that are not connected to the affected TMA(s), press 1 on the operator panel, and then press Enter (Continue function).
	5. Request service for the control unit.
	10HG A customization error occurred during IML.
	No action is required; the control unit is operational.
401 - 420	Host programming error.
	• Press RESET at the affected terminal.
	• Try the operation again.
	• If the session is terminated, initiate the session again.
421	• Request help from your technical support group or help desk. Program check; noncryptographic sessions may still be run.
721	
422 - 435	 Press RESET at the affected terminal. Follow local logon and logoff procedures to establish a noncryptographic session.
	• Perform the actions given for the status codes displayed.
	Request help from your technical support group or help desk.
	Host programming error.
	 No recovery required at the control unit or terminals.
	The session may have to be reinitiated by the host application program. • If the problem continues, call your host programmer.

- Re-IML means to try to make the control unit operational; refer to page 4-23upp. for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
436	Informational message: a late signal request or a stray response was received.
	No action required.
437 – 499	Host programming error.
	No recovery required at the control unit or terminals.
	The session may have to be reinitiated by the host application program. If the problem continues, call your host programmer.
500	No action is required, because communication is available.
501	Data communication equipment failure. Wait for the condition to clear.
	 If the problem continues, check that the modem is turned on. Check that the control unit/modem cable is connected. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
	Warning: An IML disrupts all operating terminals.
	• Run the Communication Cable Wrap Test (refer to "Communication Adapter and Communication Cable Test" on page 3-110).
	• Request service for the control unit.
503	The Channel Interface switch is offline.
	• Restore the Channel Interface switch to the Online position.
	 If the problem continues, do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). If the problem continues, request service for the control unit.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
504	01HG Disconnected from the line.
	To recover:
	• Establish the connection again.
	02HG Disconnect received.
	• Wait for the condition to clear.
	• If the condition continues, request help from your technical support group or help desk.
	03HG Normal X.21 initialization sequence.
	• Wait for the incoming call, or initiate a call.
	04HG - 06HG X.21 problem: exceeded the maximum number of retries.
	• Call again.
	07HG X.21 equipment error has been cleared.
	• Wait for the incoming call, or initiate a call.
	08HG X.21 time-out.
	• Validate the status of the X.21 network.
	09HG X.21 problem: Write Halt.
	 Record the operator panel Status display or the Communications Check number from the terminal display.
	 Use the EXT, DISC keys at the primary dial terminal to return to Call Ready mode.
	• Dial again.
	Request help from your technical support group or help desk.
	10HG X.21 problem. invalid selection sequence.
	• Record the operator panel Status display or the Communications Check number from the terminal
	 display. Use the EXT, DISC keys at the primary dial terminal to return to Call Ready mode.
	• Dial again.
	 Request help from your technical support group or help desk.
	11HG Disconnect received on a nonswitched line. This disconnection was intended for a station attached to the Token-Ring.
	Try to reestablish the connection.

505 Host connection condition.

- Wait for the condition to clear.Call the host system support if the problem continues.
- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
506	The 3174 is in the process of connecting to the X.25 network.
	 Wait for the condition to clear. If the condition continues, request help from your technical support group or help desk.
513	Communication status (X.25 call not completed).
	 If you were trying an outgoing call, try the call again. If an outgoing call was not tried, wait for the X.25 network to recover. Request help from your technical support group or help desk.
531, 532	Temporary host communication condition.
	 Wait for the condition to clear. If the condition continues, request help from your technical support group or help desk.
533	01HG X.25 Clear Packet was sent.
	To recover:
	 If outgoing calls are allowed, then initiate an outgoing call. If outgoing calls are not allowed, then wait for an incoming call to reopen the circuit.
	02HG X.25 Reset Packet was sent.
	 Wait for the condition to clear. If the condition continues, request help from your technical support group or help desk.
	03HG X.25 Restart Packet was sent.
	 Wait for the condition to clear. If the condition continues, request help from your technical support group or help desk.
	04HG X.25 Clear Packet was received.
	 If outgoing calls are allowed, then initiate an outgoing call. If outgoing calls are not allowed, then wait for an incoming call to reopen the circuit.
	05HG and 06HG X.25 Reset or Restart Packet was received.
	Wait for the condition to clear.If the condition continues, request help from your technical support group or help desk.
540	Communication status.
	 Press RESET. Try the operation again. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
	Warning: An IML disrupts all operating terminals.
	Request help from your technical support group or help desk.
541	Communication status; manual intervention required at attached display station or printer.
	Check to see that the display station is on, the security key is not locked, or the printer has paper.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
550	X.25 exception conditions.
	No action is required at the control unit or at the terminals.
551	X.25 information messages.
	No action is required at the control unit or at the terminals.
553	X.21/X.25 call establishment.
	No action is required at the control unit or at the terminals.
560, 561	X.21 communication status.
	Wait for the condition to clear.
562	01HG The X.21 'call progress' signal has been received
	Try the call again.
	02HG The X.21 network is not ready.
	No action is required at the control unit or at the terminals.
	03HG X.21 clear time-out.
	Wait for the condition to clear.
563	X.21 error condition.
	 Check the dial numbers of the Primary and of the 3174. Use the EXT, DISC keys at the terminal to return to call-ready state. Dial again. Request service for the control unit.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
580	01HG - 03HG A failure occurred during the initialization of the Token-Ring Adapter.
	• Re-IML.
	Warning: An IML disrupts all operating terminals.
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Do the Token-Ring Adapter wrap test. Request help from your technical support group or help desk.
	04HG A failure occurred during the initialization of the Token-Ring Adapter.
	• Re-IML.
	Warning: An IML disrupts all operating terminals.
	• Request help from your technical support group or help desk.
	05HG - 07HG A failure occurred during the initialization of the Token-Ring Adapter.
	• Re-IML.
	Warning: An IML disrupts all operating terminals.
	 Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Do the Token-Ring Adapter wrap test. Request help from your technical support group or help desk.
	08HG The Token-Ring is inoperative.
	Request help from your technical support group or help desk.
	58HG A temporary Token-Ring error occurred.
	If the failure continues, request help from your technical support group or help desk.
581	The Token-Ring Adapter detected a duplicate adapter address on the ring.
	A unique address must be assigned to each adapter on the ring. If the address for the 3174 must be changed, the control unit must be reconfigured.
583	02HG A Frame Reject (FRMR) was sent because an unacceptable Token-Ring frame was received.
	No action is required.
	03HG
	 Contact the host operator to return the link(s) to service. Request help from your technical support group or help desk.
	04HG - 08HG
	No action is required.
	09HG Link recovery was unsuccessful.
	 Contact the host operator to return the link(s) to service. Request help from your technical support group or help desk.

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
584	A Token-Ring Adapter counter overflowed.
	 No actions are required if the control unit is operating normally. If the control unit is not operating normally, go to the next step. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108).
	Warning: An IML disrupts all operating terminals.
	 Request help from your technical support group or help desk.
590	Communication problem at the Distributed Function Terminal.
	 Switch terminal power off, then on. Refer to the terminal Problem Determination Guide. Perform the terminal problem determination procedures.
599	Communication status (Local mode).
	Press the COMM key at the affected terminal to exit local mode.
600 - 699	1X Permanent machine check detected by a DFT.
	Refer to the terminal Problem Determination Guide.
	5X Temporary machine check detected by a DFT.
	Refer to the terminal Problem Determination Guide.
700 – 799	Program check detected by a DFT.
	Refer to the terminal Problem Determination Guide.
802	01HG Not authorized to access another host from the Connection Menu.
	Change customization to authorize access, or select the default host.
	02HG - 05HG A temporary condition is blocking your request.
	Wait for a few minutes and try again.
	06HG The PF3 (Quit) key was pressed, but the previous host to return to does not exist.
	Select a host for your return request.
	07HG
	The port connection you request already exists.
	08HG A printer powered off because it could not connect to the host.
	 Wait for a few minutes and power on. Keep trying this until a connection is made to the host. If the condition continues, request help from your technical support group or help desk.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
803	01HG The wrong keyboard was used with the 3270 terminal in session with the ASCII host.
	Use one of these supported keyboards:
	 US English Typewriter keyboards APL keyboards Text keyboards
	02HG - 03HG
	Make sure that you are using the correct entry from the Connection Menu.
	04HG An invalid key was pressed.
	 Try again. If the message is repeated, check the keyboard map found in the Terminal User's Guide, GA23-0332. Request help from your technical support group or help desk.
804	A timeout occurred in the ASCII Adapter.
	 Wait and try again. If this message recurs, request help from your technical support group or help desk.
805	An incorrect password was used.
	Follow the local recovery procedures.
806	An ASCII buffer has overrun.
	Request help from your technical support group or help desk.
807 and	The ASCII Adapter has timed out.
808	 Make sure that the terminal is turned on and its cable is connected. Verify that the ASCII port type was customized correctly. Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform the AEA Port Wrap Test on the ASCII Adapter port (HG and port) indicated in the terminal message. Request help from your technical support group or help desk.
809	The ASCII Adapter was disconnected from the terminal or host.
	Note: If this was a normal disconnect from the ASCII host, no action is required.
	 Make sure that the terminal is turned on and its cable is connected. Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform the AEA Port Wrap Test on the ASCII Adapter port (HG and port) indicated in the terminal message. Request help from your technical support group or help desk.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
810	The ASCII Adapter was disconnected from the terminal or host.
	Note: If this was a normal logoff procedure from the ASCII host, no action is required.
	 Make sure that the terminal is turned on and its cable is connected. Check the phone connection. Verify that the modem cabling is correct. Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform the AEA Port Wrap Test on the ASCII Adapter port (HG and port) indicated in the terminal message. Request help from your technical support group or help desk.
811	The ASCII Adapter has not received a Ready signal from the modem.
	 Make sure that the correct modem is installed and properly set up, and that the modem cabling is correct. Make sure that the control unit is properly customized for the modem. Run the modem manufacturer's diagnostic tests. Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform the AEA Port Wrap Test on the ASCII Adapter port (HG and port) indicated in the terminal message. Request help from your technical support group or help desk.
812	The ASCII Adapter has exhausted connection retries.
	 Make sure that the correct modem is installed and properly set up, and that the modem cabling is correct. Call the host number on a voice phone to check the remote modem. Make sure that the dial digits, specified during customization, are correct. Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform the AEA Port Wrap Test on the ASCII Adapter port (HG and port) indicated in the terminal message. Request help from your technical support group or help desk.
813	The modem has received an invalid command from the ASCII Adapter.
	 Make sure that the correct modem is installed and properly set up, and that the modem cabling is correct. Make sure that the control unit is properly customized for the modem. Make sure that the dial digits, specified during customization, conform to the modem requirements. Include pauses in the Dial String if they are required to allow for intermediate dial tones. Run the modem manufacturer's diagnostic tests. Request help from your technical support group or help desk.
814	The ASCII Adapter has not received a Character Echo from the modem.
	 Make sure that the correct modem is installed and properly set up, and that the modem cabling is correct. Make sure that the modem matches the type specified during customization. Run the modem manufacturer's diagnostic tests. Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform the AEA Port Wrap Test on the ASCII Adapter port (HG and port) indicated in the terminal message. Request help from your technical support group or help desk.

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
815	A call came in while an outgoing call was in progress.
	 Retry the call. Make sure that the modem cabling is correct. Run the modem manufacturer's diagnostic tests. Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform the AEA Port Wrap Test on the ASCII Adapter port (HGand port) indicated in the terminal message. Request help from your technical support group or help desk.
816	A 3174 ASCII Adapter received an incoming call, but the answering sequence was not completed.
	 Make sure that the modem cabling is correct. Run the modem manufacturer's diagnostic tests. Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform the AEA Port Wrap Test on the ASCII Adapter port (HG and port) indicated in the terminal message. Request help from your technical support group or help desk.
817	An ASCII status counter overflowed.
	 Use the Refresh Sequence (see the keyboard map) to request retransmission. Make sure that the parity and the number of stop bits were specified correctly during customization. Make sure that the modem cabling is correct. Run the modem manufacturer's diagnostic tests. Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform the AEA Port Wrap Test on the ASCII Adapter port (HG and port) indicated in the terminal message. Request help from your technical support group or help desk.
818	The Break key was pressed, and the session was disconnected.
	 There is no recovery action. A new connection may be requested.
819	The ASCII Adapter could nor reset the modem.
	 Make sure that the correct modem is installed and properly set up, and that the modem cabling is correct. Make sure that the control unit is properly customized for the modem. Run the modem manufacturer's diagnostic tests. Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform the AEA Port Wrap Test on the ASCII Adapter port (HG and port) indicated in the terminal message. Request help from your technical support group or help desk.

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action		
820	An ASCII Adapter communications error.		
	 Use Test 12, Option 1,2 (refer to "Procedure H - All Connections to ASCII Adapter Are Failing" on page 3-57) to perform the AEA Port Wrap Test on the ASCII Adapter port (HG and port) indicated in the terminal message. Run the modem manufacturer's diagnostic tests. Request help from your technical support group or help desk. 		
821	10HG The session was dropped because the ASCII Adapter bit rate was exceeded.		
	 If the port type is Direct or Nonswitched, press the Carriage-Return key. If the port type is Switched, dial again. If the problem continues, power the terminal OFF and ON. Request help from your technical support group or help desk. 		
•	20HG The session was dropped because the ASCII Adapter bit rate was exceeded.		
	 Select a host from the Connection Menu. Request help from your technical support group or help desk. 		
880	01HG - 03HG A failure occurred during the initialization of the Token-Ring Adapter.		
	 Contact the host operator to return the link(s) to service. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). 		
	Warning: An IML disrupts all operating terminals.		
	 Do the Token-Ring Adapter wrap test (refer to "Token-Ring Adapter and Cable Test" on page 3-114) Request help from your technical support group or help desk. 		
	04HG A failure occurred during the initialization of the Token-Ring Adapter.		
	Request help from your technical support group or help desk.		
	05HG - 07HG A failure occurred during the initialization of the Token-Ring Adapter.		
	 Contact the host operator to return the link(s) to service. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Do the Token-Ring Adapter wrap test. Request help from your technical support group or help desk. 		
	08HG The Token-Ring is inoperative – permanent beaconing.		
	Request help from your technical support group or help desk.		
	58HG		
	A temporary beaconing condition occurred on the Token-Ring.		
	If the failure continues, request help from your technical support group or help desk.		
881	The Token-Ring Adapter detected a duplicate adapter address on the ring.		
	A unique address must be assigned to each adapter on the ring. If the address for the 3174 must be changed, the control unit has to be configured again.		

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
883	01HG The gateway address or the Token-Ring Adapter address is invalid.
	Contact the system programmer.
	02HG - 08HG
	 Contact the host operator to return the link(s) to service. If the failure continues, request help from your technical support group or help desk.
	60HG
	If the control unit is not working correctly, request help from your technical support group or help desk.
884	If the control unit is not working correctly, request help from your technical support group or help desk.
890	The Ring Error Monitor has detected a problem.
	Request help from your technical support group or help desk.
1001, 1002	IML microcode failure.
	 Insert the backup Control or Utility diskette. Re-IML. Request help from your technical support group or help desk.
1003, 1004	IML hardware failure: diskette or diskette drive.
	 Insert the backup Control or Utility diskette. Re-IML. Request help from your technical support group or help desk.
1005	An Alt 1 IML was performed, using a diskette other than the Control or Utility diskette.
	 Insert the correct Control or Utility diskette. Correct the Alt 1 IML diskette selection parameter. Re-IML. Request help from your technical support group or help desk.
1011	IML microcode failure.
	 Insert the backup Control or Utility diskette. Re-IML. Request help from your technical support group or help desk.
1048 -	IML hardware failure.
1058	• Re-IML.
	• Request service for the control unit.
1060 -	IML hardware or microcode failure.
1079	 Insert the backup Control or Utility diskette. Re-IML. Request service for the control unit.

[•] Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.

<sup>When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more</sup> than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
2001 - 2087	The offline test was completed successfully.
	At the operator panel, press Enter for the 4001 prompt, or do an IML to exit testing mode.
21HG	Offline test in progress. A failure occurred if the status code does not change for more than 10 seconds.
	Note: 21HG will alternate with 22HG during the running of this test.
	 Re-IML and try the test again. Request service for the control unit.
22HG	Offline test in progress; a failure occurred if the status code does not change for more than 10 seconds.
	Note: 22HG will alternate with 21HG during the running of this test.
	 Re-IML and try the test again. Request service for the control unit.
2587	Offline tests from a Control diskette have been completed successfully.
	Note: Not all offline tests are on the Control diskette.
	Use the Utility diskette to run a complete set of tests.
	Re-IML to exit test mode.
2901 -	Offline test hardware failure.
2987	 Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. Request service for the control unit.
3001 -	Offline test hardware failure.
3012	 Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. Request service for the control unit.
3020 -	Offline test hardware failure: diskette drive or media.
3025	 Install another Utility diskette in drive 1, and then another Control diskette in drive 2, and try the test again. Request service for the control unit.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base	Possible		
Status	Additional		
Code	Numbers / Explanation / Action		

3030 01HG Offline test modem wrap failure.

- Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key.
- Perform the Communication Cable Wrap Test (refer to "Communication Adapter and Communication Cable Test" on page 3-110).
- Request help from your technical support group or help desk.

02HG Offline test communication cable wrap failure: A cable is not connected.

- Verify that the cable is a valid 3174 communication cable. Valid cable part numbers are 6168155, 6423153, 6423155, 6423157, 6423325, and 6423326.
- Verify that the cable is correctly attached.
- · Try the test again.
- Request help from your technical support group or help desk.

03HG Offline test communication cable wrap failure: An incorrect cable is connected to a Type 2 Communication Adapter.

- Connect the Type 2 cable to the Type 2 Communication Adapter. Refer to "Communication Adapter and Communication Cable Test" on page 3-110 for the port numbers.
- Request help from your technical support group or help desk.

04HG Offline test communication cable wrap failure: An incorrect cable is connected to a Type 1 Communication Adapter.

- Connect the Type 1 cable to the Type 1 Communication Adapter. Refer to "Communication Adapter and Communication Cable Test" on page 3-110 for the port numbers.
- Request help from your technical support group or help desk.

2xHG

Note: Make sure that the cable switches are set to test.

- Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key.
- Request service for the control unit.

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
- · Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions

Base Status Code	Possible Additional Numbers / Explanation / Action
3040	01HG PN00 Terminal Adapter port failed an offline wrap test. (PN = Terminal Adapter port number)
	Note: Make sure that the cable was disconnected from the port being tested.
	 Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. Request service for the control unit.
	02HG PNMP TMA/3299 port failed an offline wrap test. (PN = Terminal Adapter port number) (MP = Multiplexer port number)
	Note: Make sure that the cable was disconnected from the port being tested.
	 Request help from your technical support group or help desk.
3041	Terminal Adapter path test to a terminal has failed.
	Note: Make sure that the terminal is turned on.
	• Check the connection between the terminal and the 3174. Refer to "3270 Terminal Connection Problems" on page 3-13.
	 Request help from your technical support group or help desk.
3042	01HG PN00 Offline display/printer Exerciser test failure (path was direct). (PN = Terminal Adapter port number)
	 Refer to the display/printer Problem Determination Guide. Request help from your technical support group or help desk.
	02HG PNMP Offline Display/Printer Exerciser test failure (path through TMA/3299). (PN = Terminal Adapter port number) (MP = Multiplexer port number)
	 Refer to the display/printer Problem Determination Guide. Request help from your technical support group or help desk.
3043	Terminal Adapter has failed.
	 Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. Re-IML. Request service for the control unit.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action	
3050	01HG Offline Token-Ring Adapter cable wrap test failure; there is an open condition.	
	 Check that the Token-Ring Adapter cable is correctly attached to the adapter. If the cable is correctly connected, a problem exists in the cable path to the Token-Ring access unit or in the access unit itself. To troubleshoot, disconnect the cable at various points, except from the adapter, and retry the test. 	
	To retry the wrap test, press Enter on the operator panel, key in the test selection (3101), and press Enter. • If the cable directly connected to the Token-Ring adapter fails, then request service for the control unit.	
	02HG Offline Token-Ring Adapter cable wrap test failure; the wrap data is incorrect.	
	 Check all cable connections for proper seating; reseat any loose connections. To troubleshoot, disconnect the cable at various points, except from the adapter, and retry the test. 	
	 To retry the wrap test, press Enter on the operator panel, key in the test selection (3101), and press Enter. If the cable directly connected to the Token-Ring Adapter fails, then request service for the control unit. 	
3060, 3061	There may be a loose or disconnected internal adapter cable between the ASCII Adapter and the I/O Panel.	
	 Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. Re-IML. 	
	Request service for the control unit.	
3091 - 3170	Offline test hardware failure: storage.	
3170	 Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. Re-IML. 	
	Request service for the control unit.	
3174	Indicates that a normal IML was completed successfully, or that no error status codes are present.	
3180	Offline test hardware failure.	
	 Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. Re-IML. Request service for the control unit. 	
3201 - 3203	 IML hardware failure: FRU identification bus. Re-IML. Request service for the control unit. 	

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
3204	IML hardware configuration failure: excess storage cards.
	 If you are doing a feature installation, recheck the instructions. Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. Re-IML. Request service for the control unit.
3205	IML hardware configuration failure: invalid storage card plugging.
	For 3174 Models 1L, 1R, 2R, and 3R, a storage card is in location 17, and location 20 either is empty or has a nonstorage card installed.
	 If you are doing a feature installation, recheck the instructions. Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. Re-IML.
3220	• Request service for the control unit.
3220	 IML hardware configuration failure: invalid diskette ID. To proceed with IML, press 1 on the operator panel, and then press Enter. Request service for the control unit.
3221	IML hardware configuration failure: The Channel Adapter or Driver is missing.
	 If you are doing a feature installation, recheck the instructions. Verify that a Channel Adapter (Type 9210) is plugged into location 11 and a Channel Driver (Type 9230) is plugged into location 10. To proceed with IML, press 1 on the operator panel, and then press Enter. Request service for the control unit.
3222	IML hardware configuration failure: invalid adapter configuration.
	 If you are doing a feature installation, recheck the instructions. Verify that the cards are plugged into locations 22, 23, and 24 in the correct order and that they are valid cards. To proceed with IML, press 1 on the operator panel, and then press Enter. Request service for the control unit.
3223	IML hardware configuration failure: invalid adapter card is installed.
	 If you are doing a feature installation, recheck the instructions. Verify that the cards in locations 11 through 17 are valid. Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. These numbers identify which cards are invalid. To proceed with IML, press 1 on the operator panel, and then press Enter. Request service for the control unit.
3230 -	IML hardware failure: Terminal Adapter.
3232	 Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. To proceed with IML, press 1 on the operator panel, and then press Enter. Request service for the control unit.

Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
3233	IML hardware configuration failure.
	A Terminal Multiplexer Adapter (TMA) is installed but does not appear to be connected to a Terminal Adapter port.
	1. If you are installing a feature, press Advance twice — the first two digits in the Status display identify the card location number of the affected TMA. Repeat this procedure, recording the first two digits that appear in the Status display until the Status display is blank.
	2. Press the latch-release pushbutton on the left-center edge of the front door, and open the door (refer to Figure 2-1 on page 2-2, if necessary).
	3. Make sure that the jumper cables are correctly connected both to the Terminal Adapters (Type 915X, card locations 21, 22, and 23) and to the top coaxial connector on the associated TMAs (possible card locations are 15, 16, 11 or 23, and 12, 17, and 24).
	4. To proceed with the IML, and to bring up those terminals that are not connected to the affected TMA(s), press 1 on the operator panel, and then press Enter (Continue function).
	5. Request service for the control unit.
3234	IML hardware configuration failure: undefined ID.
	The hardware is at a higher release level than the microcode.
	 Obtain the latest level of Control and Utility diskettes and re-IML. Request help from your technical support group or help desk.
3235	The internal cable between the Token-Ring Adapter and the I/O assembly is not connected.
	Request help from your technical support group or help desk.
3250 -	IML hardware failure.
3297	• Re-IML.
	• Request service for the control unit.
3301	Offline test failure: Port 0 control terminal.
	 Check that the Port 0 control terminal is turned on. Use "3270 Terminal Connection Problems" on page 3-13 to identify connection or terminal problems. Request help from your technical support group or help desk.
3302	Offline test failure: Terminal Adapter.
	 Use the operator panel to continue testing. Run Alt 2 IML tests (refer to "Alt 2 IML Tests" on page 3-108).
3801 -	Offline test microcode failure.
3809	 Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. Insert a new diskette and try the operation again. Re-IML.
	• If the problem continues, request service for the control unit.

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
4001	Offline test prompt.
	• Key in the offline test selection. Refer to "Offline Tests" on page 3-108.
4030 - 4034	 Offline test failure. Re-IML and retry the operation. Request service for the control unit.
4050	Offline test log is full.
	At the terminal connected to port 0:
	 To retrieve the log, press Enter (Free function) to get the 4001 prompt. Key in 8001 and press Enter to display the test log. If the test log is not displayed, request help from your technical support group or help desk.
4079	Offline test failure.
	 Re-IML and retry the operation. Request service for the control unit.
4080	Offline tests are running at the display connected to port zero.
4081	Offline test failure: Port 0 control terminal.
	 Check that the Port 0 control terminal is turned on. Use "3270 Terminal Connection Problems" on page 3-13 to identify connection or terminal problems. Request help from your technical support group or help desk.
4082	Unsupported keyboard attached to port 0.
	 Connect a 3278, 3279, 3178, 3179, or similar terminal to port 0. Request help from your technical support group or help desk.
4099	Invalid procedure tried at IML error.
	The diagnostic Free and Continue functions are not allowed.
	 Re-IML. Request help from your technical support group or help desk.
4101	Invalid request keyed in the Alt 1 40 prompt.
	Note: Use the Utility diskette for offline tests or for customization.
	 Make sure that a Utility diskette is installed in the diskette drive. Do an Alt 1 IML (press and hold Alt 1, press and release IML, and then release Alt 1). Key in the correct selection at the 40 prompt. Request help from your technical support group or help desk.
4102 - 4106	 Invalid offline test request. Press Enter for the 4001 prompt. Key in the correct selection. Request help from your technical support group or help desk.

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
4107 - 4110	Operator error in pressing the wrong key during the offline tests.
	 Press the correct key. Request help from your technical support group or help desk.
4111	The response keyed in at the 3174 operator panel was not a Continue request.
	Key in 1, and press Enter.
4112	The operator did not press Alt 1 or Alt 2 correctly.
	Key in 1, and press Enter.
	• If it is not an operator problem, request service for the control unit.
4113 -	Offline test failure: the diskette drive is not ready.
4201	 Check to see that the correct diskette is inserted in all drives. Make sure that the diskette drive lever is closed on all drives. Do the Free function (press Enter). Try the test request again. If the problem continues, request service for the control unit.
4203	Offline test failure: a write-protected diskette is in the diskette drive.
	 Insert a diskette that is not write-protected and try the operation again. Request help from your technical support group or help desk.
4204	The diskette drive lever was opened and closed during the test of the drive.
	 If no one opened the drive during testing, the drive may have failed. Press Enter to do the Free function (4001 prompt). Try the test again. Request service for the control unit.
4210 -	The Terminal Adapter Printer Exerciser has detected a problem:
4212	4210: Testing an incorrect port or device.4211: Printer is out of paper, jammed, or not ready.4212: Printer is on hold or is defective.
	 Correct the condition and rerun the test. Request help from your technical support group or help desk. Press Enter to stop this test.
4505	Prompt message presented after invoking of the operator panel keypad indicator test diagnostic.
	 Press any keys and observe the Status display key indication. Press Enter to end the routine. To do the Free function, press Enter a second time.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
4510	An attached printer or display is not supported, or the wrong terminal was specified.
	 Run the test again, specifying the correct port. If the correct port was specified, connect a printer that is supported. Check modem power and cable connections. Request help from your technical support group or help desk. Press Enter to stop this test.
4511	The printer is out of paper, jammed, or not ready.
	 Check modem power and cable connections. Request help from your technical support group or help desk. Press Enter to stop this test.
4512	The print operation has not been completed; the printer Hold switch is active, or the printer is defective.
	 Check modem power and cable connections. Request help from your technical support group or help desk. Press Enter to stop this test.
4513	Responses to Communication Adapter Test: Data Set Ready and Carrier Detect are active.
	 Press Enter to stop this test. Request help from your technical support group or help desk.
4514	Response for the offline Communication Adapter Driver Static test.
	 The interface is being held active. To stop this function, press Enter (Free).
4530, 4531	Response to offline Channel Adapter Online/Offline Switch test:
	4530: The Channel Interface switch is in the Offline position.4531: The Channel Interface switch is in the Online position.
	To stop this function, press Enter (Free).
4535	IDID IDID IDID The Token-Ring Adapter Function 10 was selected for this address (IDID).
	Press Enter (Free function) to display the 4001 prompt.
4542	A prompt message to allow an update of the control unit timer day and time.
	Request help from your technical support group or help desk.
4550	01HG PN00 Offline Terminal Adapter selectable test was successful (direct path).
	02HG PN00 Offline Terminal Adapter selectable test was successful (path through TMA/3299).
4560 — 4563	Responses for the offline Diskette Drive Ready/Change Test.
	 4560: Neither Drive Ready nor Diskette Change. 4561: Drive Ready without Diskette Change. 4562: No Drive Ready with Diskette Change. 4563: Drive Ready and Diskette Change.
	If a proper status code change is not displayed when a Drive Ready or Diskette Change action occurs:
	 Request service for the control unit. Press Enter to stop this test.

[•] Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
• When requesting service, be sure to give the status code and additional numbers to the service personnel.

[•] Some status codes are normal progress or completion messages; if the **Status Code** remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
4565 -	Responses for the offline Diskette Media Scan Test.
4569	4565: Insert the diskette to be scanned, key in 1, and press Enter to start the scan. 4566: The scan was completed without any defective tracks detected. 4567: The scan was completed with defective tracks detected. Replace the diskette. 4568: Insert a valid 3174 diskette in drive 1. Rerun the test. 4569: Insert a valid 3174 diskette in drive 2. Rerun the test.
4580	The offline test log is empty.
	Press Enter (Free function) to display the 4001 prompt.
4581	The offline test log contains errors.
	At the terminal connected to port 0:
	 To retrieve the log, press Enter (Free function) to get the 4001 prompt. Key in 8001 and press Enter to display the test log. If the test log is not displayed, request help from your technical support group or help desk.
4607	The requested adapter is disabled.
	Request help from your technical support group or help desk.
4608	Online test failure: Too many users are requesting these tests.
	Wait; then retry the online test.Request help from your technical support group or help desk.
4609	Online test microcode failure.
	Retry the online test.Request service for the control unit.
4610	An invalid test number was typed in during online tests.
	Type in a valid test number from the test menu.
4611	Online Test condition: The test requested is already active.
	Try the test request again.
4612, 4613	An incorrect port number or hardware group was requested:
	4612: Enter the correct port number and retry the request.4613: Enter the correct hardware group or check that the requested group is present.
	Request help from your technical support group or help desk.
4614	An invalid entry was made during the online tests.
	Check the panel for the format that should be used, and try the test request again.
4615	The number of parameters for the online test request is incorrect.
	Check the panel that lists the desired test, and correct the test request.
4616	An invalid parameter was typed in during the online test.
	Check the panel that lists the valid parameters, and correct the test request.

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
4617	Invalid data in the online test request was typed in.
7017	Check the menu for the correct test request format, and try the test request again.
4618	The requested function is no longer supported.
4010	Request help from your technical support group or help desk.
4619	An invalid key was pressed during the online test.
	Use the correct key and retry the test request.
4620	An informational message that a system event was logged.
4020	No action is required at this time.
4625	An online test error was detected; a 8 was entered during a secondary session.
1025	 Use the ChgS key to return to the primary session. Type in /8. Press ENTER.
4630	A Start Trace command has been sent, and a trace is already running.
.020	To start the trace again:
	 Type in the Stop Trace command. Press ENTER. Then type in the Start Trace command. Press ENTER.
4631	A Stop Trace command was sent while the trace was already stopped.
4632	The control unit is busy and cannot accept the trace request.
	Try the trace request again.
4633	Trace initialization was requested after the trace was already started.
	Stop the trace, and try the trace request again.
4634	A diskette error occurred during an attempt to stop a trace.
	Use the status code on the operator panel to determine the cause of the diskette failure.
4635	A diskette error occurred during an attempt to start a trace.
	Use the status code on the operator panel to determine the cause of the diskette failure.
4636	The online trace was requested for more than two ASCII ports.
	 Traces, beyond the second requested trace, will be ignored. To run these traces, key in the Trace Stop command and set up the new ports to be traced. Request help from your technical support group or help desk.
4640	The online Port Wrap Test has been completed successfully.
4641	The requested wrap test has not been done, because a terminal is now successfully communicating with the port number that was entered in the test request.
4642	An invalid Terminal Adapter port number was typed in during the online Port Wrap Test.
	Type in 0, 8, 16, or 24 and try the test again.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
4650	The Terminal Adapter support for multiplexers $(TMA 3299)$ has failed; however, the adapter may operate when attached directly to a terminal.
	 If this port is being used for a directly attached terminal, this failure will not affect normal operation. If this port is being used to support terminals attached through a TMA/3299 multiplexer, the Terminal Adapter must be replaced. Request help from your technical support group or help desk.
4651	Terminal Adapter port wrap failure.
	This can be a false indication if the signal cable is attached to the port being tested.
	Disconnect the port signal cable, and try the test again.Request service for the control unit.
4652	Terminal multiplexer port wrap failure.
	This can be a false indication if the signal cable is attached to the port being tested.
	 Disconnect the port signal cable, and retry the test. Request help from your technical support group or help desk.
4653	A multiplexer wrap test was requested on a port that is directly connected to a terminal.
	Use the Direct Wrap Test for the Terminal Adapter port.
4660 -	An invalid entry was made in the Transmit Request from the ACA Port Test Menu.
4663	 Correct the entry and rerun the test. Request help from your technical support group or help desk. Press Enter to stop this test.
4664 -	These are messages reflecting a disconnect request from a port wrap test:
4666	 4664: The ASCII port is currently active. To force a disconnection, press Enter. 4265: A disconnection is in progress. 4266: The disconnection is completed. Press Enter to begin the wrap test originally requested.
4670	A dump of a DFT has been selected, and the DFT has not responded.
	4670 is normally followed by alternating status codes of 4671 and 4672. If this does not occur, cancel the dump by turning the DFT off, and then on.
	Start the dump again the next time the DFT fails.
4671	A dump of a DFT is in progress.
	Note: This status code alternates with 4672.
4672	A dump of a DFT is in progress.
	Note: This status code alternates with 4671.
4673	A dump of a DFT has ended before completion.
	Try the dump again. If the problem continues, do the dump the next time the DFT fails.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
4675	A dump of a DFT has been completed successfully.
	Remove the Dump diskette and insert the Downstream Load or Control diskette. Normal operations start automatically.
	If the control unit is not working correctly, request help from your technical support group or help desk.
4687	The online Token-Ring Link Status Test 9 detected an error.
	No action is required.If the operation is impaired, request help from your technical support group or help desk.
4688	The online Token-Ring Link Status Test indicates that no links are active.
	No action is required.
4689	The online Token-Ring Link Status Test indicates that the link requested is not active.
	No action is required.
4690	An invalid link address was entered during the online Token-Ring Link Status Test.
	Reenter the correct address.
4691	During an online Token-Ring Status Test, a station detected a signal loss for more than 250 milliseconds and has entered beaconing.
	Request help from your technical support group or help desk.
4692	During an online Token-Ring Status Test, the Token-Ring Adapter detected a beacon signal.
	Request help from your technical support group or help desk.
4693	A lobe wire fault was detected during the online Token-Ring Status Test.
	 Contact the host operator to return the link(s) to service. If the failure continues, request help from your technical support group or help desk.
4694	This status code indicates how long the online Token-Ring Status Test has been running.
	No action is required.
4695	This status code is displayed after the online Token-Ring Status Test has been active for 10 minutes.
	Press PF9 within the next 5 minutes to continue the test. If PF9 is not pressed, the test ends automatically.
4696	The online Token-Ring Status Test is being performed at another terminal.
	No action is required.
4697	The online Token-Ring Status Test indicates the Token-Ring Adapter is open.
	No action is required.

[•] Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
• When requesting service, be sure to give the status code and additional numbers to the service personnel.

[•] Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
4698	The online Token-Ring Status Test indicates the Token-Ring Adapter is closed.
	 Use the operator panel to see if there is another status code for hardware group 31. If there is, look up the status code in this chart and do the recommended actions. If another status code is not indicated, do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Remember, an IML disrupts all operating terminals. If the Alt 2 IML is successful, do the Token-Ring Adapter Wrap Test. If the problem continues, request help from your technical support group or help desk.
4699	The online Token-Ring Link status test indicates the links are not active.
	The station status cannot be displayed.No action is required.
4990	IML hardware or microcode failure.
	 Insert the backup Control or Utility diskette. Re-IML. Request service for the control unit.
4994	IML hardware failure: the Terminal Adapter is either defective or missing.
1994	 Re-IML. Request service for the control unit.
4995	IML failure: insufficient storage for the Control diskette configuration.
	 For diskettes configured for the Token-Ring Gateway feature, at least one Storage Expansion feature card (Type 9051 or 9052) is required in location 20. Make sure you are using the correct Control diskette. Re-IML. Request help from your technical support group or help desk.
4997	0100 Something other than 40 or 41 was entered at the Alt 1 40 prompt.
	 Try the Alt 1 IML again. Enter the correct parameters (40 or 41).
	0200 A 40 was entered with Alt 1 requesting the Master Menu with the Control diskette installed.
	 If you want a normal IML, do the Alt 1 IML and key in 41 (refer to "Making the 3174 Operational" on page 2-17). If you want the Master Menu, install the Utility diskette, do the Alt 1 IML, and key in 40 (refer to "Displaying the Master Menu" on page 2-22). Request help from your technical support group or help desk.
	0300 A 41 was entered with Alt 1 requesting a normal IML with the Utility diskette installed.
	• If you want the Master Menu, do the Alt 1 IML and key in 40 (refer to "Displaying the Master Menu" on page 2-22).
	 If you want the normal IML, install the Control diskette, do the Alt 1 IML, and key in 41 (refer to "Making the 3174 Operational" on page 2-17). Request help from your technical support group or help desk.

[•] Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.

[•] When requesting service, be sure to give the status code and additional numbers to the service personnel.
• Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
4998	An IML microcode failure.
	 Insert the backup Control or Utility diskette. Re-IML. Request help from your technical support group or help desk.
4999 – 5090	These are IML progress messages. A failure has occurred if the status code does not change in 10 seconds.
	 Exchange the Control diskette. Re-IML. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request help from your technical support group or help desk.
5201	There is a mismatch between the hardware and customization. A Channel Adapter is required for Model 1L.
	 Re-IML. Verify that you have the correct Control diskette. Request help from your technical support group or help desk.
5202	0100 There is a mismatch between the hardware and customization. Communication Adapter Type 1 is required; Models 1R, 51R, and 81R contain a Type 1 adapter.
	 Check that you are using the correct Control diskette for the correct model. Check that the Communication Adapter Type 9253 is correctly installed in location 22. Re-IML. Request help from your technical support group or help desk.
	0200 There is a mismatch between the hardware and customization: invalid or missing Type 1 communication cable.
	 Check that the communication cable is attached correctly. Check that the correct communication cable type is attached (see "Communication Adapter and Communication Cable Test" on page 3-110 for the correct part numbers). Re-IML.
5203	• Request help from your technical support group or help desk. 0100 There is a mismatch between the hardware and customization. Communication Adapter Type 2 is required; Models 2R, 52R, and 82R contain a Type 2 adapter.
	 Check that you are using the correct Control diskette for the correct model. Check that the Communication Adapter Type 9273 or 9277 is correctly installed in location 22. Re-IML. Request help from your technical support group or help desk.
	0200 There is a mismatch between the hardware and customization: invalid or missing Type 2 communication cable.
	 Check that the communication cable is attached correctly. Check that the correct communication cable type is attached (see "Communication Adapter and Communication Cable Test" on page 3-110 for the correct part numbers). Re-IML.
	• Request help from your technical support group or help desk.

[•] Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
• When requesting service, be sure to give the status code and additional numbers to the service personnel.

[•] Some status codes are normal progress or completion messages; if the **Status Code** remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
5204	0100 There is a mismatch between the hardware and customization; the Control diskette is configured for a Model 51R, 52R, or 53R.
	 Check that the correct Control diskette is installed. Re-IML. Request help from your technical support group or help desk.
	0300 There is a mismatch between the hardware and customization; the Control diskette is configured for a Model 81R or 82R.
	 Check that the correct Control diskette is installed. Re-IML.
	Request help from your technical support group or help desk.
5206	There is a mismatch between the hardware and customization: a Token-Ring Adapter is required. Models 3R, 53R, and 1L with the Token-Ring Gateway feature have a Token-Ring Adapter.
	 Check that you are using the correct Control diskette for the correct model. Check that the Token-Ring Adapter Type 9350 is correctly installed in the control unit. Request help from your technical support group or help desk.
5207	There is a mismatch between the hardware and customization: there is not enough storage to support the attachment of the Token-Ring Adapter Gateway feature.
	 Check that the correct Control diskette is installed. Re-IML.
	Request help from your technical support group or help desk.
5230	An IML customization failure: the Control diskette has not been configured.
	 Check that the correct Control diskette is installed. Re-IML. Request help from your technical support group or help desk.
5231 — 5242	IML customization failure. The Control diskette must be recustomized.
	 Insert the backup Control diskette. Re-IML.
	Request help from your technical support group or help desk.

<sup>Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status Code	Possible Additional Numbers / Explanation / Action
5243	0100 IML customization failure: Question 121 and the Keyboard Definition Utility language ID do not match.
	Note: The Keyboard Definition Utility must be used to correct the language ID.
	 Insert the backup Control diskette. Re-IML. Request help from your technical support group or help desk.
	0200 IML customization failure: Question 137 contains an invalid keyboard ID.
	Note: The Keyboard Definition Utility must be used to correct the keyboard ID.
	 Insert the backup Control diskette. Re-IML.
	Request help from your technical support group or help desk.
	0400 IML customization microcode failure.
	 Insert the backup Control diskette. Re-IML.
5044	• Request service for the control unit.
5244 — 5252	 IML customization failure. Keep pressing the Advance key until the display is blank, and record all the numbers that appeared in the Status display each time you pressed the key. Insert the backup Control diskette. Re-IML. Request help from your technical support group or help desk.
5286 - 5290	IML customization failure. The Control diskette must be recustomized. IML customization microcode failure.
	 Insert the backup Control diskette. Re-IML. Request service for the control unit.
5901, 5902	A control unit offline dump is in progress. A failure occurred if the status code does not change for more than 10 seconds.
	Status codes 5901 and 5902 will alternate during the dump.
	 The dump may be retried by starting the Alt 1 IML Dump Procedure again. Try another Dump diskette. Request service for the control unit.
5903 - 5905	A control unit offline dump is in progress. A failure occurred if the status code does not change for more than 10 seconds.
	Note: The microcode to be dumped has been destroyed.
	 Dump must be done again at the next failure. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.

- Re-IML means to try to make the control unit operational; refer to page 2-17 for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
- Some status codes are normal progress or completion messages; if the **Status Code** remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
5907	This is an offline dump prompt.
	Insert the Control diskette in the Dump diskette drive.
5908, 5909	A control unit offline dump is in progress. A failure occurred if the status code does not change for more than 10 seconds.
	Status codes 5908 and 5909 will alternate during the dump.
	Note: The microcode to be dumped has been destroyed.
	 Dump must be done again at the next failure. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
5910	This is an offline dump prompt.
	Replace the Control diskette with the original Dump diskette.
5912, 5913	A control unit offline dump is in progress. A failure occurred if the status code does not change for more than 10 seconds.
	Status codes 5912 and 5913 will alternate during the dump.
	Note: The microcode to be dumped has been destroyed.
	 Dump must be done again at the next failure. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
5914	This is an offline dump prompt: The Dump diskette is full.
	Replace the Dump diskette with a new Dump diskette.
5916	This is an offline dump prompt: The dump was completed without an error.
	 Remove the Dump diskette. The control unit can now be made operational (refer to "Making the 3174 Operational" on page 2-17).
5917, 5918	This is an offline dump prompt: The dump was completed with an error.
	 Press Advance and record the numbers in the Status display. Repeat this process until the display is blank. Remove the Dump diskette. The control unit can now be made operational (refer to "Making the 3174 Operational" on page 2-17).
5920	Incorrect offline IML dump. The Alt 1 IML Dump procedure was not invoked correctly.
	Note: The microcode to be dumped has been destroyed.
	 The dump must be done again at the next failure. Use the correct Alt 1 IML Dump procedure. Request service for the control unit.
5922	Recoverable Dump diskette error.
	 The dump may be retried by starting the Alt 1 IML Dump Procedure again. Try another Dump diskette. Request service for the control unit.

- Re-IML means to try to make the control unit operational; refer to page 4-52upp. for the correct actions.
 When requesting service, be sure to give the status code and additional numbers to the service personnel.
 Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
5923	Unrecoverable Dump diskette error.
	Note: The microcode to be dumped has been destroyed.
	 The dump must be done again at the next failure. Try another Dump diskette. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
5924, 5925	Offline dump hardware error.
	Note: The microcode to be dumped has been destroyed.
	 The dump must be done again at the next failure. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request service for the control unit.
5932	QLHG The wrong diskette was inserted for the offline dump.
	 Insert the correct diskette: QL = 01 = Insert the Control diskette. QL = 02 = Insert the original Dump diskette. QL = 03 = Insert a new Dump diskette. Request service for the control unit.
7000 -	Configuration status code.
7079	Refer to the 3174 Customizing Guide.
7080	The customizing terminal (on port 0) is not communicating with the control unit.
	 Check that the terminal is switched on. Check that the terminal cable is connected correctly.
	Note: If the terminal is attached by a 7232 Dual Control Unit Terminal Multiplexer, use the ChgSc key to display the connection to the customizing control unit.
	• Refer to the terminal Problem Determination Guide.
7081	An unsupported terminal is connected to port 0.
	Connect a 3278, 3279, 3178, 3179, or similar terminal to port 0.
7082	01HG The customizing terminal (on port 0) is either disconnected from the control unit or switched off.
	 Check that the terminal is switched on. Check that the terminal cable is connected correctly. Refer to the terminal Problem Determination Guide. Refer to "Initial Symptom/Action Table" on page 3-3.
	02xx The terminal connected to port 0 is logically disconnected from the control unit because of terminal or terminal cable errors.
	 Check that the terminal cable is connected correctly. Refer to the 2xx status code for recommended actions. Refer to "Initial Symptom/Action Table" on page 3-3.

[•] Re-IML means to try to make the control unit operational; refer to page 4-53upp. for the correct actions.

<sup>When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>

Base Status	Possible Additional Numbers / Explanation / Action
7083 7100 -	Numbers / Explanation / Action
	An invalid request was received from the customizing terminal (on port 0) port 0. Check that a 3278, 3279, 3178, 3179, or similar terminal is attached to port 0.
7449	 An error was detected during customization. Make sure that the customization questions were answered correctly. Refer to the 3174 Customizing Guide. Request help from your technical support group or help desk.
7501	RPQs were moved to a new disk.
	Reapply the RPQ, if necessary. The Merge RPQ Utility may be needed to delete old RPQs and to apply new releases containing updated versions.
7502	During a microcode upgrade, the Modified Keyboard file was not upgraded.
	 Perform the Modified Keyboard function if you want a modified keyboard. Refer to the 3174 Customizing Guide. Request help from your technical support group or help desk.
7503	During a microcode upgrade, errors were found during updating of panels.
	 Reconfigure. Refer to the 3174 Customizing Guide. Request help from your technical support group or help desk.
7504	Not able to upgrade the Printer Authorization Matrix (PAM).
	 Redo the PAM procedure. Refer to the 3174 Customizing Guide. Request help from your technical support group or help desk.
7505	During a microcode upgrade, errors were found during updating of AEA panels.
	 Redo the AEA configuration procedure. Refer to the 3174 Customizing Guide. Request help from your technical support group or help desk.
7521	The Encrypt/Decrypt Adapter is not present.
	Open the front door, and verify that the Encrypt/Decrypt Adapter is installed in card location 24.
	 If the adapter is installed, run Alt 2 IML tests (refer to "Alt 2 IML Tests" on page 3-108). If the adapter is not installed, you were trying to do an Encrypt/Decrypt utility on a control unit that does not have the feature.
7522 and 7523	Configuration status code.
	Refer to the 3174 Customizing Guide.
7524	Encrypt/Decrypt Adapter error.
	 Insert the security key into the Encrypt/Decrypt Adapter and turn it to the horizontal position. Then, turn it back to the vertical position. Try the utility again. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Replace the battery on the Encrypt/Decrypt Adapter. Then call your system security supervisor to install the master key value (procedures in the 3174 Customizing Guide). Request help from your technical support group or help desk.

<sup>Re-IML means to try to make the control unit operational; refer to page 4-54upp. for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.</sup>

[•] Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.

Base Status Code	Possible Additional Numbers / Explanation / Action
7525	Encrypt/Decrypt Adapter error.
	 Insert the security key into the Encrypt/Decrypt Adapter and turn it to the horizontal position. Then, turn it back to the vertical position. Try the utility again. Do an Alt 2 IML (refer to "Alt 2 IML Tests" on page 3-108). Request help from your technical support group or help desk.
7526 – 7529	Configuration status code.
	Refer to the 3174 Customizing Guide.
7530	Either the Encrypt/Decrypt Adapter keylock is in the wrong position or the adapter is bad.
	 Make sure that the keylock is in the vertical position, and try the operation again. Request help from your technical support group or help desk.
7531	The Encrypt/Decrypt Diskette has not yet been initialized with either a CID value or a Verify Pattern.
	 Invoke Option 1. If Option 1 has already been invoked, reinsert the diskette that was installed when that invocation took place. The current Encrypt/Decrypt diskette is not the one that was used when Option 1 was originally invoked.
7541 – 7899	A customizing status code.
	Refer to the 3174 Customizing Guide.
7900 - 7999	An internal 3174 control unit error.
	Request service for the control unit.
8888	8888 appears when the IML pushbutton is pressed.
	This is an indicator test.
	Note: If you are not pressing IML, and 8888 is displayed, the control unit has a hardware failure.
	Request service for the control unit.

<sup>Re-IML means to try to make the control unit operational; refer to page 4-55upp. for the correct actions.
When requesting service, be sure to give the status code and additional numbers to the service personnel.
Some status codes are normal progress or completion messages; if the Status Code remains lit for more than 10 seconds, the code indicates an error. For an error, perform the appropriate actions.</sup>